


PROGRAM NO. 05007



Q. Write a CNC Part Program for the figure shown

For side milling, take speed 1200 rpm & feed 100 mm/min
For drilling holes, take speed 1200rpm & feed 80mm/min
For slot milling, take speed 1200rpm & feed 120mm/min
Take hole diameter as 15mm

Use absolute coordinate system.

Solution:

Sequence of operation:

- 1 Set ref point, coordinate system, tool, give feed & speed value
- 2 Set cutter for radius compensation left offset
- 3 set tool at A, start spindle & give down feed (-Z direction)
- 4 proceed further cutting of side milling and stop spindle at A
- 5 Move tool at ref point & set the tool for slot cutting
- 6 Move tool to P, start the spindle & give down feed
- 7 Proceed further cutting of slot milling and stop spindle at S
- 8 Move tool at ref point & set the tool for drilling
- 9 Move tool to P, start the spindle & give full depth cut
- 10 Move tool up & stop the spindle.
- 11 Bring back tool at reference point.
- 12 End of the program

CNC Codes	Description
05007	Program No.
N001 G71 G90	Set dimension type mm, set absolute co-ordinate system
N002 G92 X-15.0 Y-15.0 Z0.0 T01 F100 S1200	Set reference point at 'O' (-15, -15, 0). Use tool T01(here side milling tool. Set Feed 100mm/rev, set spindle speed 1200 rpm
N003 G41 G00 X0.0 Y0.0 Z2.0	Cutter radius compensation - left ON, move the tool at A & give clearance of 2mm before starting spindle rotation
N004 G01 Z-15.0 M03	Start the spindle. Move tool down i.e. at Z direction for cut with feed (here M03 will execute first)
N005 G01 X0.0 Y110.0	Go to B linearly
N006 G02 X10.0 Y120.0 R10.0	Go to C with clockwise circular interpolation with radius = 10
N007 G01 X75.0	Go to D linearly
N008 G01 X100.0 Y92.0	Go to E linearly
N009 G01 Y10.0	Go to F linearly

CNC Codes					Description
N010	G02	X90.0	Y0.0	R10.0	Go to G with clockwise circular interpolation with radius = 10
N011	G01	X0.0			Go to A linearly
N012	Z2.0	M05			Go up 2mm in Z direction for clearance. Stop spindle rotation (here M05 will execute last).
N013	G40	G00	X-15.0	Y-15.0	Cutter radius compensation OFF. Move tool to reference set point.
N014	M06	T02	F120		Change the tool & use tool T02 (here for slot mill tool with dia 6mm). Set feed as 120mm/rev.
N015	G00	X15.0	Y55.0		Move tool to 'P' rapidly.
N016	G01	Z-5.0	M03		Start the spindle. Move tool 5mm down i.e. at Z direction for cut with feed (here M03 will execute first)
N017	Y80.0				Go to Q linearly.
N018	X85.0				Go to R linearly.
N019	Y80.0				Go to S linearly.
N020	Z2.0	M05			Go up 2mm in Z direction for clearance. Stop spindle rotation (here M05 will execute last).
N021	G00	X-15.0	Y-15.0		Move tool to reference set point.
N022	M06	T03	F80		Change the tool & use tool T03 (here for drill bit with dia 15mm). Set feed as 80mm/rev.
N023	G00	X50.0	Y25.0		Move tool to 'T'
N024	G01	Z-20.0	M03		Go down 20mm for assuring full depth of hole.
N024	Z2.0	M05			Go up 2mm in Z direction for clearance. Stop spindle rotation (here M05 will execute last).
N025	G00	X-15.0	Y-15.0		Move tool to reference set point.
N026	M30				Stop the program